

# **SANYO**

SANYO Australia Pty Ltd

*CONSUMER ELECTRONICS DIVISION*

**TECHNICAL BULLETIN No. 77    DATE: 13/05/08**

***SUBJECT: DVR-DX600 NO PICTURE OR DISTORTED***

**Fault:**

Picture distorted tearing, goes black and white. Eventually no picture at all.

**Cause:**

C823 in power supply circuit.

**Remedy:**

Replace C823 with a 470uF 25V electrolytic capacitor.