

# SANYO

SANYO Australia Pty Ltd

CONSUMER ELECTRONICS DIVISION

**TECHNICAL BULLETIN No. 86 DATE: 23/12/10**


**SUBJECT: PDP42XR9DA Preparation for Transport**

**Fault:**

Many of this model get damaged during transport.

**Cause:**

Impact/pressure on Stand Column cause panel to crack.



**Remedy:**

Remove the Stand Column and pack it separately, with its screws, within the carton box securely.

**Method:**

Remove the four screws holding the Stand Column and slide it out of the chassis.



SCREWS



STAND COLUMN