

# Notice

# SANYO

- CORRECTION       PRODUCTION CHANGE  
 SERVICE FLASH       ADD INFORMATION

FILE NO.

Please add this notice to the Service Manual listed below.

<b>Category : <u>Desktop Audio System</u></b>	<b>Date : <u>Dec. 2003</u></b>
<b>Model : <u>DTA-150</u></b>	
<b>Destination : <u>AU</u></b>	<b>Reference No. : <u>SM5810326</u></b>
	<b>Issue Number : <u>1</u></b>

The reason of change.

A : Misprint

B : Quality Reliabilities

C : Standardization

D : Design

E :

F :

Page & Section	Ref. No.		Part No.	Description	Q'ty	Interchangeability	Reason
PARTS LIST(PAGE 7)	IC201	OLD	645 048 8238	IC 5V43-1J15	1		
CD MAIN/AMP P.W.BOARD ASSY	IC201	NEW	645 065 8631	IC 5V43-1J15 with soft	1		

**PRODUCT CODE No.**  
**129 616 08**