

## Notice

<input checked="" type="checkbox"/> CORRECTION	<input type="checkbox"/> PRODUCTION CHANGE
<input type="checkbox"/> SERVICE FLASH	<input type="checkbox"/> ADD INFORMATION
<input type="checkbox"/>	<input type="checkbox"/>

FILE NO.
----------

Please add this notice to the Service Manual listed below.

Category : <u>DVD Video Player</u>	Date : <u>Dec. 2003</u>
Model : <u>DVD-SL33</u>	
Destination : <u>AU</u>	Reference No. : <u>SM5810463</u>
	Issue Number : <u>1</u>

The reason of change.

A : Misprint

B : Quality Reliabilities

C : Standardization

D : Design

E :

F :

G :

Page & Section	Ref. No.		Part No.	Description	Q'ty	Interchangeability	Reason
PARTS LIST(PAGE 5)	10	OLD	614 328 3874	ASSY PWB YUV OUT	1		
YUV OUT P.W.BOARD ASSY	10	NEW	614 329 6102	ASSY PWB YUV OUT	1		
PARTS LIST(PAGE 6)	U0104	OLD	645 064 0209	IC SST39VF800	1		
MAIN P.W.BOARD ASSY	U0104	NEW	645 065 8617	IC SST39VF800 with soft.	1		
PARTS LIST(PAGE 6)	16	OLD	614 328 8015	ASSY PWB POWER	1		
POWER P.W.BOARD ASSY	16	NEW	614 329 9028	ASSY PWB POWER	1		

PRODUCT CODE No.

137 121 03