

SANYO

SANYO Australia Pty Ltd

CONSUMER ELECTRONICS DIVISION

TECHNICAL BULLETIN No. 40

DATE: 24/11/1999

SUBJECT: DCD-40 POWER TRANSFORMER

The above model power transformer Part No. 614 249 7081 is no longer available and can be substituted by the one from DCF 280 Part No. 614 017 2731.

As the pin-out of the new transformer is slightly different from the original. The following modifications need to be carried out on the P.T. Secondary P.C.B.

- Cut the track between Pin 1 of the power transformer and pin 2 of CN792 as indicated on the diagram below.
- Relocate R4932 between Pin 1 CN793 and Pin 1 of the power transformer. Drill a small hole near Pin 1 of the transformer, or move the resistor to the copper side of the P.C.B. Refer to the diagram below.

