

SANYO

SANYO Australia Pty Ltd

CONSUMER ELECTRONICS DIVISION

TECHNICAL BULLETIN No. 43 DATE: 4/5/2000

SUBJECT: PLCSU 20 AV DISPLAY FAULT

FAULT: The picture in AV mode only will display two narrow bands of video.

CAUSE: Service Mode adjustment Item: **68** is set to **12**.

REMEDY: Put the projector in "Service Mode" by following the instructions in the Service Manual. Set the Service Mode adjustment Item: **68** to **537**.