


CIRCUIT DIAGRAMS & PRINTED WIRING BOARDS

TABLE OF CONTENTS

BLOCK DIAGRAMS & CIRCUIT DIAGRAMS	Page
OVERALL BLOCK	C3
U101, U102, U103 BLOCK	C3
SENSOR BOARD CIRCUIT	C3
MAIN BOARD CIRCUIT	C4
PRINTED WIRING BOARDS (P.W.B.)	
SENSOR P.W.B.	C9
MAIN P.W.B.	C9

PRODUCT SAFETY NOTICE

THE COMPONENTS DESIGNATED BY A SYMBOL () IN THIS SCHEMATIC DIAGRAM DESIGNATES COMPONENTS WHOSE VALUE ARE OF SPECIAL SIGNIFICANCE TO PRODUCT SAFETY. SHOULD ANY COMPONENT DESIGNATED BY A SYMBOL NEED TO BE REPLACED, USE ONLY THE PART DESIGNATED IN THE PARTS LIST.
DO NOT DEVIATE FROM THE RESISTANCE, WATTAGE AND VOLTAGE RATINGS SHOWN.