


7 8 9 10 11 12



1 2 3 4 5 6 ϕ

A

B

C


D

E

F

G


H



TO K90A TO K90B

TO ass'y RS232C

ASSY,PWB,CGMOT



SCHEMATIC DIAGRAM S2