

Notice



CORRECTION

PRODUCTION CHANGE

SERVICE FLASH

ADD INFORMATION

FILE NO. _____

REVISION-4

Please add this notice to the Service Manual listed below.

Category : Multi-media Projector	Issued Date : June / 2008
Model : PLC-XU115	Effective from : Chassis No. KF3-XU11500
Destination : Canada, U.S./Europe, Asia, U.K.	REF. NO. : SM5110954

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual.

If the Chassis. No. does not match the unit's, additional Service Literature is required. Only the difference service information is given in this manual. For detailed service information, refer to the service manual original SM5110954-00 issued in April 2008 for Model PLC-XU115.

The reason of change.

A : Misprint B : Quality Reliabilities C : Standadization D : Designm

Page	Key No.		Part No.	Description	Q'ty	Interchange-ability	Reason
P74	LP900	False	610 336 0058	COMPL, OPTICAL LAMP A KM6AC	1	NO	A
		True	610 333 9740				

FILE WITH ORIGINAL SERVICE MANUAL (SM5110954)

PRODUCT CODE

1 122 386 00 (KF3AC)

1 122 387 00 (LF3AC)

1 122 387 02 (LF3CC)

REFERENCE NO. SM5110954-04