

# Notice



CORRECTION

PRODUCTION CHANGE

SERVICE FLASH

ADD INFORMATION

FILE NO.

REVISION-1

Please add this notice to the Service Manual listed below.

<b>Category :</b> Multi-media Projector	<b>Issued Date :</b> Nov. / 2008
<b>Model :</b> PLC-XU115	<b>Effective from :</b> Chassis No. KF3-XU11500
<b>Destination :</b> Canada, U.S./Europe, Asia, U.K.	<b>REF. NO. :</b> SM5110954

**NOTE:** Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual.  
**If the Chassis. No. does not match the unit's,** additional Service Literature is required. Only the difference service information is given in this manual. For detailed service information, refer to the service manual original SM5110954-00 issued in April 2008 for Model PLC-XU115.

## The reason of change.

A: Misprint B: Quality Reliabilities C: Standadization D: Design

Page		Key No.	Part No.	Description	Q'ty	Interchange-ability	Reason
P74	False	A2000	665 002 3582	ASSY,PWB,NETWORK,KF3AC	1	NO	A
	True	A2300	655 002 3582	ASSY,PWB,NETWORK,KF3AC	1		

**FILE WITH ORIGINAL SERVICE MANUAL (SM5110954)**

### PRODUCT CODE

**PLC-XU115**

**1 122 386 00** (KF3AC)

**1 122 387 00** (LF3AC)

**1 122 387 02** (LF3CC)

REFERENCE NO. SM5110954-05