

- CORRECTION
- PRODUCTION CHANGE
- SERVICE FLASH
- ADD INFORMATION

**FILE NO.**

Please add this notice to the Service Manuals listed below.

Revision 2

<p>■ Category : Multimedia projector</p> <p>■ Model No. : <b>PLC-XF30</b> <b>PLC-XF30N</b> <b>PLC-XF30NL</b></p> <p>■ Destination : Canada, Europe, Asia, Africa, M.E., U.K. U.S.A., Canada U.S.A.</p>	<p>■ Date : Dec./ 2003</p> <p>■ Effective from Chassis No. : MY6-XF3000 MY6-XF30N00 MY6-XF30NL00</p> <p>■ Ref. No. : SM5110295</p>
--	--

■ The correction of Model number (Reason: Misprint)

	Before Correction	After Correction
<b>Cover Page</b>	<p><b>FILE NO.</b></p> <p><b>MODEL NO.</b></p> <p><b>PLC-XF30</b> (Projection lens is optional.) Canada, Europe, Asia, Africa, M.E., U.K.</p> <p><b>PLC-XF30N</b> U.S.A., Canada</p> <p><b>PLC-XF30L</b> (Projection lens is optional.) U.S.A.</p>	<p><b>FILE NO.</b></p> <p><b>MODEL NO.</b></p> <p><b>PLC-XF30</b> (Projection lens is optional.) Canada, Europe, Asia, Africa, M.E., U.K.</p> <p><b>PLC-XF30N</b> U.S.A., Canada</p> <p><b>PLC-XF30NL</b> (Projection lens is optional.) U.S.A.</p>

Before : PLC-XF30L

After : PLC-XF30NL

**PRODUCT CODE :**

PLC-XF30	MY6A	1 122 105 00	U.S.A. , Canada
PLC-XF30	MY6AB	1 122 105 40	U.S.A. , Canada
PLC-XF30	PY6A	1 122 106 00	Continental Europe, Asia, Africa, M.E.
PLC-XF30	PY6AB	1 122 106 40	Continental Europe, Asia, Africa, M.E.
PLC-XF30	PY6C	1 122 106 02	U.K.
PLC-XF30	PY6CB	1 122 106 42	U.K.
PLC-XF30N	MY6AA	1 122 105 20	U.S.A. , Canada
PLC-XF30N	MY6AC	1 122 105 60	U.S.A. , Canada
PLC-XF30NL	MY6AL	1 122 105 30	U.S.A. , Canada
PLC-XF30NL	MY6AM	1 122 105 70	U.S.A. , Canada

REFERENCE NO. SM5110295-02